



Bill Trier

PAGE 1 OF 10

Collector Vehicle Appraisals

PROFESSIONAL APPRAISING IN FLORIDA SINCE 1980

PRE-BUY INSPECTIONS - INSURANCE - FINANCING - LITIGATION - ESTATES - RESALE

270 SOUTHLAND ROAD, VENICE, FLORIDA 34293 - MAILING ADDRESS: P.O. BOX 2134 VENICE, FL 34284

OFFICE: 941-408-9601 CELL: 941-223-1556 WEB: www.floridaclassiccarappraisals.com

CLIENTS NAME DALE WILKINSON APPRAISAL DATE 3/20/24 TIME 9:00 AM
 STREET 5733 FOSSANO DR CITY SARASOTA STATE FL ZIP 34238
 BUSINESS _____ HOME _____ CELL 941-891-2769 FAX _____

YEAR 1962 MAKE CHEVROLET MODEL CORVETTE BODY STYLE CONV
 VIN NUMBER 20867S111261 COLOR (S) FAWV BEIGE
 ENGINE 327/340 V8 TRANSMISSION 4 SPD MANUAL MILEAGE SHOWING 63375
 AUTO ☒ TRUCK ☐ STREETROD ☐ OTHER THIS IS AN APPRAISAL NOT A PREBUY INSPECTION
 BUILD SHEET AVAILABLE ☐ DOCUMENTED RECEIPTS AVAILABLE ☐ PHOTO(S) ALBUM AVAILABLE ☐

OVERALL ANALYSIS OF VEHICLE

CONDITION CODES: 1-EXCELLENT 2-FINE 3-VERY GOOD 4-GOOD 5-RESTORABLE 6-PARTS CAR

VEHICLE CONDITION

+2

CURRENT VALUE OF VEHICLE

\$110,000

THE CURRENT MARKET VALUE OF THIS VEHICLE HAS BEEN CALCULATED FROM UP-TO-DATE CURRENT TRADE PUBLICATION REFERENCES, AUCTION REPORTS, DEALER AND PRIVATE SALES AS RECORDED IN PUBLICATIONS AS "OLD CARS PRICE GUIDE", "NADA PUBLICATIONS", "KELLEY BLUE BOOK", "OLD CARS WEEKLY", AND OTHER RELIABLE SOURCES WHICH ARE RECOGNIZED AND ACCEPTED BY THE MAJOR INSURANCE COMPANIES AND FINANCIAL INSTITUTIONS WORLD WIDE AS WELL AS BY PROSPECTIVE BUYERS AND SELLERS OF COLLECTOR VEHICLES AND COURTS OF LAW.

AFTER PRE-BUY INSPECTION BUYER SHOULD PERSONALLY INSPECT AND DRIVE VEHICLE BEFORE PURCHASING TO INSURE COMPLETE SATISFACTION.
 OPERATING AND COSMETIC CONDITIONS OF THIS VEHICLE MAY CHANGE AT ANY TIME IMMEDIATELY AFTER THIS INSPECTION.

IMPORTANT!! THIS REPORT AND TEST DRIVE AS OF THE DATE ON TODAY'S REPORT REVEALS HOW THE CAR RAN AND DROVE AFTER A BRIEF TWO MILE DRIVE AND TWO HOUR INSPECTION. KEEP IN MIND THAT THIS VEHICLE AND MOST COLLECTOR VEHICLES ARE OLD OR OLDER OR MODIFIED USED VEHICLES EVEN IF FULLY RESTORED. THEY CAN BE SUBJECT TO ANY TYPE OF MECHANICAL, COSMETIC, STRUCTURAL OR ELECTRICAL PROBLEMS OF ANY KIND IMMEDIATELY AFTER A TEST DRIVE IS PERFORMED OR ANY TIME THEREAFTER. THE INSPECTOR CANNOT GUARANTEE ANY COLLECTOR VEHICLE AS TO NOT HAVING ANY PROBLEMS. EVEN A BRAND NEW VEHICLE HAS A FACTORY WARRANTY SINCE NEW VEHICLES AND CAN BE PRONE TO PROBLEMS.

APPRAISAL WRITTEN BY: William S. Trier DATE: 3/20/24

CONTENTS

ANALYSIS (OVERALL) OF VEHICLE
 COSMETIC APPEARANCE EXTERIOR

PAGE 1
 PAGE 2

MECHANICAL CONDITION ACCESSORIES (OPERATING) PAGE 8
 MECHANICAL CONDITION BRAKE SYSTEM PAGE 8
 MECHANICAL CONDITION BRAKE SYSTEM CONTINUED PAGE 9
 MECHANICAL CONDITION COOLING SYSTEM PAGE 9
 MECHANICAL CONDITION ELECTRICAL SYSTEM PAGE 9
 MECHANICAL CONDITION FUEL SYSTEM PAGE 10
 MECHANICAL CONDITION STEERING SYSTEM PAGE 10
 MECHANICAL CONDITION SUSPENSION SYSTEM PAGE 10
 APPRAISERS CREDENTIALS PAGE 10

Bill Trier

Collector Vehicle Appraisals

INSURANCE • ESTATES • LITIGATION
 PRE-BUY INSPECTIONS • ARBITRATION
 DONATIONS • DIMINISHED VALUE



AUTO-TRUCKS-CUSTOMS-STREET RODS-MOTORCYCLES-MILITARY-PROFESSIONAL VEHICLES
 DOMESTIC AND FOREIGN 1900 TO PRESENT

LICENSED APPRAISING IN FLORIDA
 ALL STATEWIDE LOCATIONS-SINCE 1988

B (941) 681-2521 C (941) 223-1556
 9304 ANITA AVE., UNIT B • ENGLEWOOD, FL 34224

Email: trier@comcast.net

Web: floridaclassiccarappraisals.com

erved. This form may not be reproduced or quoted in whole or in part by mimeograph or any other printed or electronic means, or for on from William S. Trier, Bill Trier Collector Vehicle Appraisals, P.O. Box 2134, Venice, Florida 34284.